



P*		E min		G min		Tmin	
psi	bar	inch	mm	inch	mm	inch	mm
1500	103	3.75	95	2.13	54	2.01	51
2000	138	4.50	115	2.44	62	2.24	57

P\* = Charging pressure



CR

<b>Max Speed</b> 315 ft/min 1,6 m/s	32 - 176 °F 0 - 80 °C	N2	<b>P max</b> 2000 psi 138 bar	<b>P min</b> 363 psi 25 bar	<b>S</b> 5.14 in <sup>2</sup> 33,18 cm <sup>2</sup>	
---	--------------------------	----	-------------------------------------	-----------------------------------	---	--

PART NUMBER	F0 Initial Force		Cu		L		L min			
	4 ton 4000 daN	5 ton 5000 daN	inch	mm	inch	mm	inch	mm	~ lb	~ Kg
CR 5000 - 0.50 - A			0.50	12,7	1.91	48,5	1.41	35,8	5.50	2,49
CR 5000 - 0.75 - A			0.75	19,0	2.41	61,2	1.66	42,2	6.01	2,72
CR 5000 - 1.00 - A			1.00	25,4	2.91	73,9	1.91	48,5	6.54	2,97
CR 5000 - 1.50 - A			1.50	38,1	3.91	99,3	2.41	61,2	7.53	3,42
CR 5000 - 2.00 - A			2.00	50,8	4.91	124,7	2.91	73,9	8.57	3,89
CR 5000 - 2.50 - A			2.50	63,5	5.91	150,1	3.41	86,6	9.59	4,35
CR 5000 - 3.00 - A			3.00	76,2	6.91	175,5	3.91	99,3	10.60	4,81
CR 5000 - 3.50 - A			3.50	88,9	7.91	200,9	4.41	112,0	11.62	5,27
CR 5000 - 4.00 - A			4.00	101,6	8.91	226,3	4.91	124,7	12.63	5,73
CR 5000 - 4.50 - A			4.50	114,3	9.91	251,7	5.41	137,4	13.65	6,19
CR 5000 - 5.00 - A			5.00	127,0	10.91	277,1	5.91	150,1	14.67	6,65
CR 5000 - 5.50 - A			5.50	139,7	11.91	302,5	6.41	162,8	15.71	7,13
CR 5000 - 6.00 - A			6.00	152,4	12.91	327,9	6.91	175,5	16.72	7,59
CR 5000 - 6.50 - A			6.50	165,1	13.91	353,3	7.41	188,2	17.71	8,04
CR 5000 - 7.00 - A			7.00	177,8	14.91	378,7	7.91	200,9	18.76	8,51

<b>HOW TO ORDER</b> p. 17	<b>ACCESSORIES</b> p. 47	<b>SERVICE TOOLS</b> p. 68 Part Number 58UT047A	<b>MAINTENANCE KIT</b> Part Number 39BMCR05000A
------------------------------	-----------------------------	--	--